



OH 1 3



Position on LED Scan


Very deep rectangular dent




OH 1 47



Large inhomogeneity in
diffusive coating





The fill as seen by LED Scan

Tile ID: OH-2-47

